

PDFVCE



Choose the version that fits your needs	PDF Version	Desktop Test Engine	Online Test Engine
Latest and Up-to-Date exam dumps with real exam questions answers.	✓	✓	✓
Get 12-Months free updates without any extra charges.	✓	✓	✓
Experience same exam environment before appearing in the certification exam.	✗	✓	✓
100% exam passing guarantee in the first attempt.	✓	✓	✓
20% discount on more than one license and 30% discount on 5+ license purchases.	✗	✓	✓
100% secure purchase on SSL.	✓	✓	✓
Completely private purchase without sharing your personal info with anyone.	✓	✓	✓

<http://www.pdfvce.com>

Highly Efficiently Exam Tool and Effective Exam Practice Materials

Exam : **H12-421**

Title : Huawei Certified Network
Professional-Data Center
Facility-Build Facility
Deployment Optimization

Vendor : Huawei

Version : DEMO

NO.1 The following air conditioning systems need to be equipped with a cooling tower or dry cooler ().

- A. CW air-cooled type
- B. DX water-cooled type
- C. Direct ventilation air conditioning system
- D. DX air-cooled type

Answer: B

NO.2 In the "Video" function of NetEco, you can perform operations such as (). (Multiple Choice)

- A. Modify the camera
- B. Delete the camera
- C. Create a camera
- D. Video live browsing

Answer: A,B,C,D

NO.3 In the Huawei NetCol5000-A line-class precision air conditioner, the () parts are optional.

- A. Evaporator
- B. Compressor
- C. Fan
- D. Electric heating

Answer: D

NO.4 In the case of normal mains, the UPS battery in inverter mode may be executed (). (Multiple choice)

- A. Balanced charging
- B. Float charging
- C. Checking the capacity test
- D. Shallow discharge test

Answer: A,B,C,D

NO.5 The FusionModule1000B series solution can meet the Tier4 power supply requirements when using the 2N power supply and distribution system.

- A. True
- B. False

Answer: B

NO.6 ECC800 is the core component of the micro-module local management, and its south-facing components can be extended through the PoE bus.

- A. FALSE
- B. TRUE

Answer: B

NO.7 When the Huawei air-cooled air-conditioning compressor is turned on for the first time, the

crankcase heating belt needs to be warmed up for more than () hours.

- A. 24
- B. 2
- C. 6
- D. 12

Answer: D

NO.8 Huawei Fusion Module2000 monitoring system supports users on which to monitor the status of micro-modules? (Multiple choice)

- A. ECC 800Web interface
- B. PAD APP
- C. NetEco web interface
- D. Mobile APP

Answer: A,B,C,D

NO.9 In the installation scenario where the indoor unit is higher than the outdoor unit, the oil trap must be set.

- A. True
- B. False

Answer: B

NO.10 Which of the following factors affect battery life? (Multiple Choice)

- A. Rated capacity
- B. Temperature
- C. Number of cycles
- D. Depth of discharge

Answer: B,C,D

NO.11 The UPS5000-E accepts input voltage frequency in a range of () Hz.

- A. 45-70
- B. 40-70
- C. 50-60
- D. 55-65

Answer: B

NO.12 The same group of batteries cannot be mixed with batteries of different capacities, different specifications, different batches, and different manufacturers.

- A. TRUE
- B. FALSE

Answer: A

NO.13 When inspecting, maintaining and repairing electrical equipment in non-blackout mode, a warning sign or signage should be placed on the electrical installation and work area.

A. False

B. True

Answer: B

NO.14 When the ECC800 detects that the connection signal to the device is interrupted, a communication interruption alarm is generated. What are the possible reasons? (Multiple choice)

A. Equipment failure

B. Cable connection is loose

C. Poor cable contact

D. Power supply is not normal

Answer: A,B,C,D

NO.15 Which of the following components do not support wireless networking?

A. Skylight actuator

B. AC actuator

C. ETH converter

D. Access control actuator

Answer: C

NO.16 In the naming of UPS5000-E-120K-HASBS, the letter E stands for ().

A. Input switch type is ATS

B. 208V voltage system

C. E series modular UPS

D. Input switch type is MCCB

Answer: C

NO.17 The UPS5000 option temperature and humidity sensor does not support cascading.

A. True

B. False

Answer: B

NO.18 The operation noise of the NetCol5000-A air conditioning unit is abnormal. It should be checked whether the compressor, fan, pipeline, etc. are fixed normally and there is looseness.

A. True

B. False

Answer: A